## **BUND SEALER**

#### **AREAS OF USE**

- Chemical & oil storage and bund areas
- · Plant rooms
- · Walls and floors
- · Indoors and outdoors



#### **FEATURES**

- · One coat, high build, epoxy resin bund sealer
- Forms a waterproof barrier to seal and protect against oil, petrol, diesel and chemical spillages
- Can be used with Watco Fibreglass Reinforcing Tape to fill cracks and joints between the bund wall and the floor to prevent leaks
- · Withstands heavy traffic
- Contains glass flake reinforcement for even greater resistance to chemical attack
- Provides excellent protection to metal tanks and pipes
- Helps comply with The Control of Pollution (Oil Storage) Regulation
- Can be applied at temperatures as low as 5°C
- Virtually solvent free suitable for confined spaces
- Superior performance demonstrated by ISO testing to CE Mark EN1504-2

#### **DESCRIPTION**

Watco has developed a one coat, high build, virtually solvent free, epoxy resin bund sealer which seals and protects bunded areas against spillages of water, oil, petrol and diesel.

This advanced formulation contains glass flake reinforcement which provides excellent resistance against chemical attack. Watco Bund Sealer cures to form a hard surface film which withstands heavy traffic.

One thick brush applied coat is generally sufficient, although two coats may be required on porous, open textured surfaces or to achieve a watertight seal over wider cracks and joints. Vulnerable cracks and joints, such as between the wall and floor, can also be further strengthened using Watco Fibreglass Reinforcing Tape.

Watco Bund Sealer is suitable for use both indoors and outdoors and will cure at temperatures as low as 5°C.

Watco Bund Sealer carries CE Mark EN1504-2 and has excellent test results for chemical resistance. It also has an A+ VOC emissions rating with a low level of VOC.

SPECIFICATION COLOURS

Composition	Glass reinforced, high solids, epoxy resin.
Number of Components	2
Finish	Smooth and glossy.
Primer Required	No.
Number of Coats	Usually 1.
Dry Film Thickness	300 microns.
Wet Film Thickness	300 microns.
Usage Interior/ Exterior	Interior & exterior.
Application Tools	Paint brush.
Minimum Application Temperature	Air Temperature 10°C. Floor Temperature 5°C.
Suitable For	Bricks, blockwork, concrete, sand and cement, asphalt and small areas of metal. The moisture content of concrete should be less than 75% RH.
Pack Size	4L
Coverage	14m²
Pot Life	25 mins @ 20°C.
Mix Ratio (by weight)	100 parts resin : 36 parts curing agent.

Shelf Life Cleaning	discarded after use.  24 months in unopened containers.  Watco Bio D.  Between 15°C-25°C for at least 8
Storage	hours prior to use. Do not allow to freeze.
Principle Limitations Please contact us regarding applications not described here.	Do not apply to a wet surface or areas subject to rising damp. Do not apply to areas subject to movement such as structural movement or around vibrating machinery.

Heavy Traffic: Regular forklift, heavy footfall, parked vehicles

	Bla	ck	
Sampl availal reques While g with the shown, can be	ble o st. great o e colo no gu given	eare is our sar uarante that t	nples ee hey
represe			he

**Light Grey** 

CURING TIME	Recoat Time	Touch Dry	Light Traffic	Heavy Traffic	Chemical Resistance
5°C	36 hours	24 hours	48 hours	72 hours	14 days
10°C	16 hours	12 hours	24 hours	48 hours	7 days
20°C	10 hours	6 hours	12 hours	48 hours	7 days
Light Traffic: Foot, trolley	, pallet truck, o	ccasional forkli	ft		

#### **TEST RESULTS**



# Abrasion Resistance ISO 5470-1

Taber test method expresses results in mg on a scale between 0mg (highest resistance) and 3000mg (lowest). A reading below 3000mg is a CE mark pass.

3000mg → 0mg Lowest → Highest



#### Flexibility ISO 1519

Flexibility is measured using a Mandral Flex Tester, 2mm is the most flexible, 36mm the least.





#### Impact Resistance ISO 6272

Impact is expressed as Newton metres. Greater than 4 Nm is a CE mark pass. Class 1 >4Nm Class 2 >10Nm

Class 3 >20Nm

GLOSS VALUE

#### Gloss Value

Rating is a 'Gloss Unit' measured on an Optical Glossmeter.

Matt 0-10%, Low Sheen 10-25%, Eggshell 26-40%, Semi-Gloss 41-69%, Gloss 70-85%, High Gloss +85%



### Scratch Resistance ISO 4586-2


Scratch resistance is measured using a Sclerometer and the resistance is measured in Newtons. 1N is the lowest resistance, 20N the highest.





#### Wolff-Wilborn Hardness Test


Also known as the 'pencil test', a 9H reading is the measure of a hardest coating, HB is the softest.





#### Adhesion Test ISO 2409

Cross-Cut Test method. Class 0 is highest adhesion, Class 5 is lowest.





## Water Permeability EN 1062-3

To achieve a CE mark, the measurement must be less than 0.1 kg/m²(24 h)0.5

CE Marking
Critical Value:
< 0.1kg/m²/(24 h)

W<sub>1</sub>

W<sub>2</sub>

W<sub>3</sub>

W<sub>4</sub>

W<sub>4</sub>

W<sub>4</sub>

W<sub>4</sub>

W<sub>5</sub>

W<sub>4</sub>

W<sub>4</sub>

W<sub>7</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>

W<sub>8</sub>


W<sub>9</sub>

W<sub></sub>



#### Adhesion Test EN 1542

Adhesion is expressed in MegaPascals (MPa) or Newton millimetres squared (Nmm²). Greater than 2 MPa is a CE mark pass.





#### Slip Resistance BS7976-2

The Pendulum Test Value (PTV) is measured in wet conditions.
A number above 36 indicates a 'low slip potential'.

W<sub>1</sub> → W<sub>2</sub> → W<sub>3</sub> Lowest Highest

High: 0-24 PTV

Moderate: 25-35 PTV

Low: 36+ PTV



#### **Chemical Resistance**

Results shown, in the table below, are for tests with commonly used chemicals based on a 72 hour period of attack. Advice can be given for chemicals not listed here.

Best long term	
resistance	

Oxalic Acid 10%
Tartaric Acid 20%
Calcium Hydroxide 50%
Sodium Hypochlorite 15%
Sodium Hydroxide 50%
Butoxvethanol

Low Aromatic White Spirit Odourless Kerosene White Spirit Sodium Chloride Solution 50% Sugar Solution 50% Mineral Oil Ethanol Ester Alcohol Anti-Freeze Acetone Brine Bleach Good long term resistance Nitric Acid 20% Sulphuric Acid 20% Hydrochloric Acid 15% Ammonia 20% Naphtha C9

Ethyl Methyl Ketone Detergent Skydrol Petrol Diesel Some attack, limited resistance only Acetic Acid 20% Phosphoric Acid 20% Lactic Acid 10%

Not resistant Xylene Benzyl Alcohol Solvent based paint stripper

## STANDARD COMPLIANCE



#### EN 1504-2

This mark indicates that a coating has passed all the tests required to carry a CE mark.



#### BREEAM COMPLIANT



#### VOC LEVEL



### ISO 16000

The 'Loi Grenelle' measurement of the effect of a product's VOC level within a building. A+ is the top safety rating.



#### REACH COMPLIANT

#### SURFACE PREPARATION

Bare blockwork, brick and concrete – ensure surfaces are clean, dry and dust free. Usually a good sweep with a stiff broom or brush is sufficient. Any grease or oil contamination should be removed using Watco Concroff. For larger areas of bare concrete, Watco Etch & Clean can be used to remove weak cement deposits.

New concrete – as a guide, new concrete should be left for eight weeks to dry.

Painted surfaces – abrade to remove any weak or loose paint. Check remaining paint is well bonded. Very smooth, glossy paint should be lightly abraded to provide a key. Watco Bio-D can be used to remove grease and oil from painted surfaces. Watco Concroff is a very powerful degreaser for contaminated bare concrete, (do not use on a previously painted surface since it can soften paint).

Priming – is not usually required, but for open textured, or very porous high suction surfaces, such as sand and cement screed or porous bricks or blocks, a second coat may be required.
Minor cracks/joints – such as between the wall and floor, can be strengthened by using

Watco Fibreglass Reinforcing Tape. Push the tape firmly into place on top of the wet Bund Sealer so that the crack or joint runs down the centre of the tape. Push the tape onto the layer of Bund Sealer using a brush loaded with more Bund Sealer. Work the tape into the corners, joint and angles, ensuring good contact with the surface at all joints. If a join is required, overlap the tape by at least 50mm and work in as above. Allow to harden and apply more Bund Sealer over the rest of the bund or area to be sealed.

Large cracks/joints – will need repairing prior to applying Bund Sealer. Please contact our Technical Department for advice.

MIXING: Remove the two inner tins from the tall outer tin. Stir the contents of each tin thoroughly and pour all of the contents into the outer tin, (scrape around the inside of the tins to remove any residue). Mix the components together thoroughly using a spatula or similar wide bladed tool, (a piece of wooden batten is ideal) and do not thin. Continue mixing until an even consistency is obtained. Do not mix more than one pack at a time. If a paint stirrer fitted to an electric drill is used, also use the spatula to blend in any unmixed material from the sides and bottom of the tin.

APPLICATION: Important – once the contents of the pack have been mixed, a chemical reaction takes place which creates heat, and the product should therefore be used immediately.

Best results are obtained in warm (minimum of  $15^{\circ}$ C), dry conditions with good ventilation. Apply one thick coat with a paint brush working well into the surface. Do not exceed the maximum coverage of  $14m^2$  per 4 litre pack.

Do not wash or allow water to lie on the surface for at least 7 days.

SAFETY: Material Safety Data Sheets are available.

ORDERING: Available direct from Watco UK Limited and through agents worldwide. All Watco products are sold subject to the Company's Standard Conditions of Sale. The Company and its representatives are often asked to comment on potential uses of Watco products which differ from those described in the Company's data sheets. Whilst in such cases the Company and its representatives will always try to offer helpful and constructive advice, the Company cannot be held responsible for the results of such uses unless they are specifically confirmed in writing by Watco.













#### WATCO.CO.UK